SF82 DEW-POINT TRANSMITTER

A rugged dew-point transmitter for continuous measurement in industrial dryer applications

Product Orde	ring Code {Fea	ture A}+{Feature B}+{Feature C}+{Feature D}+{Feature E}	
Feature	Item	Description	
Feature (A)	Base Model		
	SF82-TX	A rugged dew-point transmitter for continuous measurement in industrial dryer applications	
Feature {B}	Туре		
	B1	G1/2" BSP Process Connection	
	B2	3/4" UNF Process Connection	
	В3	5/8" UNF Process Connection	
Feature {C}	Range		
	C1	-60/+60°Cdp output scaled 4-20mA range	
	C2	-50/+50°Cdp output scaled 4-20mA range	
**	C3	-50/+30°Cdp output scaled 4-20mA range	
	C4	-80/+20°Cdp output scaled 4-20mA range	
	C5	-20/+50°Cdp output scaled 4-20mA range	
Feature {D}	Protection		
	D1	Standard HMWPE guard (for protection against fine particulates (<10 µm))	
Feature {E}	Electrical Connector		
	E1	MiniDIN 43650	
	E2	M12 5 Pin	
** - Non-star	ndard scaled ra	nges available upon request	

Ordering Example

ISEX7-1X+B1+(1+D1+F1	SF82 Transmitter, 2-wire, 4-20mA output, G 1/2" BSP, measurement range -60 to +60°Cdp, HMWPE guard, MiniDin 43650
----------------------	---

SF82 DEW-POINT TRANSMITTER ACCESSORIES AND SPARE PARTS

Order Codes	Product / Description
Spares	
SF82-HMP	Pack of 10 replacement HMWPE guards (for protection against fine particulates <10µm)
SSG	SS sintered guard replacement (for protection against fine particulates <80µm)
SSF-PF-10PK	Pack of 10 particulate filter cartridges (for protection against fine particulates < 0.1µm (for Sampler Kits))
GEN-LABEL	Additional/replacement transmitter labels (price per 2 off labels)
BS-12-PK5	G1/2" Bonded Seal for process connection (pack of 5)
OR-34-PK5	3/4" UNF Viton O-ring for process connection (pack of 5)
BS-58-PK5	5/8" UNF Bonded Seal for process connection (pack of 5)
EA2-SC	MiniDIN sensor connector socket
EA2-SCG	Sensor Connector MiniDIN Gasket
Sampling Accessories	
APT-PAN	5/8" UNF (Internal) to 3/4" UNF (External) Adapter Collar
APT-GEI	5/8" UNF (Internal) to G1/2" (External) Adapter Collar
APT-TSO	5/8" UNF (Internal) to 1/2" NPT (External) Adapter Collar
SB-12	G1/2" SS sample block (with 1/8" NPT inlet & outlet ports)
SB34-SF82	SS 3/4" sample block (with 1/8" BSP and 1/4" BSP ports)
SB-12-QF	G 1/2" Quick Fit Sample Block with DN7.2 Quick Connector for compressed air. Outlet vent to atmosphere
SB-58-QF	5/8" UNF Quick Fit Sample Block with DN7.2 Quick Connector for compressed air. Outlet vent to atmosphere
APT-KF40-34	KF40 Adaptor Flange for ¾ UNF Sensors
APT-KF40-58	KF40 Flanschplatte für 5/8" UNF Sensoranschluß
CSB	5/8" UNF SS sample block (with 1/8" NPT inlet & outlet ports)
EA2-SAM	5/8" UNF Sampler Kit (for atmospheric or pressure dp measurements, 145 psig/10 barg max)

Humidity and Dew-Point Instruments

EA2-SAM-HP	5/8" UNF HP (High Pressure) Sampler Kit - (for atmospheric or pressure dp measurements, 2900 psig/200 barg max)	
PTFE-xx	PTFE sample tube 6mm (0.24") O/D thick-walled (for Sampler Kit) $(xx = length of tube in meters - price per meter- above 0.5m)$	
EA2-BLC-FIL	Easidew Sampling Block / Filter (with 1/8" NPT inlet & Outlet ports)	
EA2-BLC-FIL-NPT	Easidew Sampling Block / Filter (with 1/4" NPT inlet & Outlet ports)	
Electrical Accessories		
EA2-CAB-0.8	Cable, 0.8m (2.62') length with MiniDIN 43650 mating socket	
EA2-CAB-02	Cable, 2m (6.56') length with MiniDIN 43650 mating socket	
EA2-CAB-05	Cable, 5m (16.4') length with MiniDIN 43650 mating socket	
EA2-CAB-10	Cable, 10m (32.8') length with MiniDIN 43650 mating socket	
EA2-M12-CAB-0.8	Sensor Cable, 0.8m (2.62') with M12 Sensor Connector	
EA2-M12-CAB-02	Sensor Cable, 2m (6.56') with M12 Sensor Connector	
EA2-M12-CAB-05	Sensor Cable, 5m (16.4') with M12 Sensor Connector	
EA2-M12-CAB-10	Sensor Cable, 10m (32.8') with M12 Sensor Connector	
Other cable lengths available upon request		

SER2 DEW-POINT TRANSMITTER SERVICE EXCHANGE

Order Codes		Product / Description		
Product Orde	ring Code {Featu	re A}+{Feature B}+{Feature C}		
Feature (A)	Base Model			
	SF82-TX-X	Service exchange, reconditioned SF82 (supplied with traceable calibration certificate, old sensor to be returned to MIL in 21 days)		
Feature {B}	Туре			
	B1	G1/2" BSP Process Connection		
	B2	3/4" UNF Process Connection		
	В3	5/8" UNF Process Connection		
Feature {C}	Range			
	C1	-60/+60°Cdp output scaled 4-20mA range		
	C2	-50/+50°Cdp output scaled 4-20mA range		
	C3	-50/+30°Cdp output scaled 4-20mA range		
	C4	-80/+20°Cdp output scaled 4-20mA range		
	C5	-20/+50°Cdp output scaled 4-20mA range		
**	(v/wx-yz)	Non-standard measurement range: v = zero value, w = full scale value, x = unit (C = °Cdp, F=°Fdp, P=ppmV) y = Pressure for ppmV conversion in bar/psi, z = pressure unit (PG=psig, PA=psia, BG=barg, BA=bara) blank = 0 barg/psig) e.g. 0-100ppm @ 10barg = 0/100P-10BG		
Feature {D}	Protection			
	D1	Standard HMWPE guard (for protection against fine particulates (<10 µm))		
Feature {E}	Electrical Connector			
	E1	MiniDIN 43650		
	E2	M12 5 Pin		
** - Non-star	ndard scaled rang	es available upon request		
5 Pin mating connector is not supplied with the product and should be ordered separately from the accessories list				

SF82 CALIBRATION SERVICES

OI OI GIAILIDIGATION OILANIGIS		
SF82-TX-Recal	Recalibration of SF82 Transmitter (Supplied with traceable calibration certificate)	
READINGS-DPS	Readings before calibration (calibration data recorded before adjustment) - Dew-Point Sensors	

Please note: Michell Instruments adopts a continuous development program which sometimes necessitates specification changes without notice. Please contact us for latest version. Issue No: SF82_99974_V5_UK_0223